



Change AP430 Filter:

1. Shut off incoming water supply.
2. Open nearest hot water outlet for 10 seconds to relieve pressure.
3. Remove cartridge by unscrewing counterclockwise from tee.
4. Replace with new AP431 cartridge.
5. Turn on water supply